

Figure 3. Limestone formations of Northern Guam.





Figure 4. Barrigada Village ponding basin, location of sampling sites B1c and B1e.




Figure 5. Barrigada Heights ponding basin #2, location of sampling site B2w.





Figure 6. Barrigada Heights ponding basin #3, location of sampling site B3.



Figure 7. Latte Heights Estates ponding basin #2, location of sampling site L2.





Figure 8. Latte Heights Estates ponding basin #3, location of sampling site L3.



Figure 9. Perez Acres ponding basin.





Figure 10. Mariana Terrace ponding basin.



Figure 11. Airport Road drainage ditch at sampling location.






Figure 12. East Agana Bay storm drain sampling location.



Figure 13. Naval Air Station storm drain outlet and delta.






Figure 14. West Agana Bay storm drain outlet.



Figure 15. Camp Watkins Road drainage ditch at sampling location.





Figure 16. Groundwater seepage at Naton Beach, Tumon Bay.